


QUANTITY
FACTOR

- 1 A = 1 ~~49~~ x 49
- 2 B = 1.18 ~~49~~ x (3+6+6) = 9
- 3 C = 1.04 ~~49~~ x (6+6+6+6+6+6) = 36
- 4 D = 1.10 ~~49~~ x (6+6+6+6) = 18
- 5 E = 1.03 ~~49~~ x (6+6+3+6+6+6) = 27
- 6 F = 1.19 ~~49~~ x (6+6+6) = 12
- 7 G = 1.14 ~~49~~ x (6+6+6+6+6) = 24
- 8 H = 1.20 ~~49~~ x (6+6) = 6
- 9 I = 1.13 ~~49~~ x (6+6+6) = 12
- 10 J = 1.17 ~~49~~ x (6+6) = 6
- 11 K = 1.02 ~~49~~ x (6+6+6+6) = 18
- 12 L = 1.07 ~~49~~ x (6+6+3+6+6) = 27
- 13 M = 1.23 ~~49~~ x (6+6) = 6
- 14 N = 1.11 ~~49~~ x (3+6) = 3
- 15 O = 1.16 ~~49~~ x (6+6) = 6
- 16 P = 1.06 ~~49~~ x (6+6+3+6) = 21
- 17 Q = 1.22 ~~49~~ x (6+6+6+6) = 18
- 18 R = 1.15 ~~49~~ x (6+6) = 6
- 19 S = 1.21 ~~49~~ x (6+6) = 6
- 20 T = 1.12 ~~49~~ x (6+6) = 6
- 21 U = 1.05 ~~49~~ x (6+6+3+6) = 18
- 22 V = 1.01 ~~49~~ x (6+6) = 6
- 23 W = 1.08 ~~49~~ x (6+6+6) = 12
- 24 X = 1.09 ~~49~~ x (6+6) = 12



FACET DIAGRAM
15 FREQUENCY